

# Inspection Photos

11/19/2018

Operator: DIVERSIFIED OPERATING  
CORPORATION - 24461

Location ID: 408511

Inspection Doc. Number: 682504203  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: DIVERSIFIED OPERATING CORPORATION - 24461  
Location ID: 408511



**Photo 1:** Photo taken from the east end of the location, facing west. Photo shows location/access road has not been reclaimed. Adjacent reference crop land





**Photo 2:** Photo taken from the east end of the location, facing west. Photo shows location/access road has not been reclaimed. Adjacent reference crop land



Inspection Photos  
Operator: DIVERSIFIED OPERATING CORPORATION - 24461  
Location ID: 408511



**Photo 3:** Photo taken from the location, facing north. Photo shows equipment and risers remain on location.





**Photo 4:** Photo taken from the west end of the location, facing north. Photo shows pit appears to have been filled.





**Photo 5:** Photo taken from the west end of the former pit. Photo shows various pipe and trash debris remaining.





**Photo 6:** Photo taken from the west end of the former pit. Photo shows various pipe and trash debris remaining.





**Photo 7:** Photo taken from the west end of the location, facing east. Photo shows location/access road has not been reclaimed. Adjacent reference crop land