

Inspection Photos

11/19/2018

Operator: WALSH* FRANK H - 94100

Location ID: 405947

Inspection Doc. Number: 682504205

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC




Photo 1: Photo taken from the location, facing north. Photo shows risers have been removed and additional reclamation activities appear to have been conducted.



Photo 2: Photo taken from the location, facing west. Photo shows risers have been removed and additional reclamation activities appear to have been conducted.



Photo 3: Photo taken from the location, facing north. Photo shows risers have been removed and additional reclamation activities appear to have been conducted.