

Inspection Photos
Location Name: Schmidt #2
API: 05-083-06256



Schmidt #2 well head.



Produced water AST in secondary containment. Two approximately 900 gallon tanks are in use until repairs to pit are complete.

Inspection Photos
Location Name: Schmidt #2
API: 05-083-06256



Pit #112977, currently not in use.



Monitoring wells installed for REM #11138.

Inspection Photos
Location Name: Schmidt #2
API: 05-083-06256



Production equipment on Schmidt #2 location.



Liner in Pit Facility ID #112977.