

Inspection Photos
Location Name: Nate Springs 3
Location ID: 05-103-09822
Inspection: 679701826



Photo 1. Location looking north.




Photo 2. Wellhead not venting. No valve below cellar. Valve above cellar closed.