

Inspection Photos
Location Name: UPPR HAYES 15
Location ID: 05-103-07084
Inspection: 679701834



Photo 1. Location looking northeast.



Inspection Photos

Location Name: UPPR HAYES 15

Location ID: 05-103-07084

Inspection: 679701834



Photo 2. Well head



Photo 3. Casing open to atmosphere in cellar.

