

Inspection Photos

Location Name: HILL, CARRIE & DON 5

Location ID: 05-103-06356

Inspection: 679701836




Photo 1. Location looking north.



Inspection Photos

Location Name: HILL, CARRIE & DON 5

Location ID: 05-103-06356

Inspection: 679701836



Photo 2. Well head



Photo 3. Gas collection bags attached to both vent openings.

