

Inspection Photos

Loc#452797

Operator: Laramie

Inspection Number: 692400377

Inspection Date: 11/19/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from top of Cut Slope to West.

November 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson 05 Loc#452797



Photo#2:
View from base of slope of failed BMP area 10/16/18.




Photo#3:
View from base of slope of repaired BMP area 11/19/18.

November 19, 2018



Photo#4:
View of fill slope to East of failed BMP Area 10/16/18

November 19, 2018



Photo#5:
View of fill slope to East of repaired BMP Area 11/19/18.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson 05 Loc#452797



Photo#6:
View over capped drain outlet 10/16/18.

November 19, 2018



Photo#7:
View over capped drain outlet 11/19/18.



Photo#8:

It was noted that Cut slope soils are starting to erode/migrate down slope and mix with top of Cuttings which are stored at base of, & draped up Cut slope.

November 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson 05 Loc#452797