

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2018

Submitted Date:

11/22/2018

Document Number:

692400377**FIELD INSPECTION FORM**

Loc ID 452797	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1401 SEVENTEENTH STREET #1400</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452788	WELL	DG	10/01/2018		077-10508	BCU 0993-21-05E	RI
452789	WELL	DG	10/26/2018		077-10509	BCU 0993-21-01E	RI
452790	WELL	DG	10/22/2018		077-10510	BCU 0993-21-02E	RI
452791	WELL	DG	10/09/2018		077-10511	BCU 0993-21-04W	RI
452792	WELL	DG	09/28/2018		077-10512	BCU 0993-21-05W	RI
452793	WELL	DG	08/31/2018		077-10513	BCU 0993-21-09E	RI
452794	WELL	DG	09/16/2018		077-10514	BCU 0993-21-07E	RI
452795	WELL	DG	10/30/2018		077-10515	BCU 0993-21-01W	RI
452796	WELL	DG	09/03/2018		077-10516	BCU 0993-21-08E	RI
452798	WELL	DG	10/13/2018		077-10517	BCU 0993-21-03W	RI
452799	WELL	DG	10/04/2018		077-10518	BCU 0993-21-04E	RI
452800	WELL	DG	09/19/2018		077-10519	BCU 0993-21-06E	RI
452801	WELL	DG	08/28/2018		077-10520	BCU 0993-21-09W	RI
452802	WELL	DG	08/24/2018		077-10521	BCU 0993-21-10W	RI
452803	WELL	DG	08/20/2018		077-10522	BCU 0993-21-10E	RI
452804	WELL	DG	10/17/2018		077-10523	BCU 0993-21-02W	RI
452805	WELL	DG	09/23/2018		077-10524	BCU 0993-21-06W	RI
452821	WELL	DG	09/07/2018		077-10525	BCU 0993-21-08W	RI
452831	WELL	DG	09/12/2018		077-10526	BCU 0993-21-07W	RI

General Comment:

This is a Reclamation / Stormwater focused Inspection, a Follow Up to Insp Doc#692400233 Dated 10/16/18. FIR Resolution forms were submitted for the CAs in previous RI Inspection. This Inspection report verifies that previous RI CAs have been resolved. This Inspection does not absolve any CAs from Environmental Inspections. Drill Rig is no longer on Location; it appears installation of Facilities was in progress at time of Inspection.

Inspected Facilities				
Facility ID: <u>452788</u>	Type: <u>WELL</u>	API Number: <u>077-10508</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452789</u>	Type: <u>WELL</u>	API Number: <u>077-10509</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452790</u>	Type: <u>WELL</u>	API Number: <u>077-10510</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452791</u>	Type: <u>WELL</u>	API Number: <u>077-10511</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452792</u>	Type: <u>WELL</u>	API Number: <u>077-10512</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452793</u>	Type: <u>WELL</u>	API Number: <u>077-10513</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452794</u>	Type: <u>WELL</u>	API Number: <u>077-10514</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452795</u>	Type: <u>WELL</u>	API Number: <u>077-10515</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452796</u>	Type: <u>WELL</u>	API Number: <u>077-10516</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452798</u>	Type: <u>WELL</u>	API Number: <u>077-10517</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452799</u>	Type: <u>WELL</u>	API Number: <u>077-10518</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452800</u>	Type: <u>WELL</u>	API Number: <u>077-10519</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452801</u>	Type: <u>WELL</u>	API Number: <u>077-10520</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452802</u>	Type: <u>WELL</u>	API Number: <u>077-10521</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452803</u>	Type: <u>WELL</u>	API Number: <u>077-10522</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452804</u>	Type: <u>WELL</u>	API Number: <u>077-10523</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452805</u>	Type: <u>WELL</u>	API Number: <u>077-10524</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452821</u>	Type: <u>WELL</u>	API Number: <u>077-10525</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>452831</u>	Type: <u>WELL</u>	API Number: <u>077-10526</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Silt Fences	Pass					
Sediment Traps	Pass					
Ditches	Pass					
Compaction	Pass					
Berms	Pass					

Comment: BMP repairs & installations required by previous RI CAs have been completed. Materials are no longer stored at site; resolving the Materials Handling issue. It was noted that Cut slope soils are starting to erode/migrate down slope and mix with top of Cuttings which are stored at base of, & draped up Cut slope. Refer to Photo Log attached.

Corrective Action: Stabilize upper area of Cut slope & soils above Cuttings; installing appropriate BMPs per Rule 1002.f.

Date: 12/21/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692400378	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4653795