

Inspection Photos

API#077-08021

Operator: Black Hills

Inspection Number: 692400056

Inspection Date: 11/21/2018





Photo#1:
Overview of Location to Northwest.

November 21, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Bernard API#077-08021



Photo#2:
Overview of Location to Southeast.

August 20, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Bernard API#077-08021



Photo#3:

View of vegetation in center area of site; arrow indicates windrow of mowed weeds.

August 20, 2018



Photo#4:
Views of weedy areas of Location; arrow indicates windrow of mowed weeds.

Photo#5:

August 20, 2018



Photo#6:
Close up of ground conditions at site.

Photo#7:

August 20, 2018