

# Final Reclamation Inspection

November 20, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-15535

Inspection Document #: 682404233

Weld County, CO

SESW Section 32 T5N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: REIN #BB32-14  
API: 05-123-15535



**Photo 1.** Photo taken from the battery location (non-cropland), facing West. Appears the Operator has started to perform final reclamation activities but Remediation Project #10881 is still active. Operator shall continue to monitor and control weeds and stormwater until the location meets Rule 1004 standards during the remediation process. Well location and access road were fallow cropland so a future final reclamation inspection will be conducted.



**Photo 2.** Non-cropland reference photo taken north of the battery location, facing North. Appears the battery location will be brome plant species based off its location, whereas, the well location and access road are cropland.