

**Inspection Photo
Harris RWF 433-5
API # 045-13733
Inspection # 689302420**



Location Photo #1



Location Photo #2

**Inspection Photo
Harris RWF 433-5
API # 045-13733
Inspection # 689302420**



Location Photo #3



Location Photo #4, Domestic tap

**Inspection Photo
Harris RWF 433-5
API # 045-13733
Inspection # 689302420**



Location Photo #5, unused /unmarked flowlines.



Location Photo #6, Stained soil near wellhead.