

Inspection Photos
Location Name: MILLARD 1
Location ID: 333131



PHOTO 1: WELLHEAD

PHOTO 2: TANK BATTERY

Inspection Photos
Location Name: MILLARD 1
Location ID: 333131



PHOTO 3: STAINED SOIL AROUND WELLHEAD



PHOTO 4: STAINED SOIL NEAR SEPARATOR