

Inspection Photos

API#077-08401

Operator: OXY USA : Laramie

Inspection Number: 692400391

Inspection Date: 11/19/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South.

November 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: OXY / Laramie PA Bradshaw-Dolley API#077-08401



Photo#2:
Overview of Location to Northeast.

November 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: OXY / Laramie PA Bradshaw-Dolley API#077-08401



Photo#3:

Unknown flowline/pipeline riser #1 remaining on Location at North end of site.

November 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: OXY / Laramie PA Bradshaw-Dolley API#077-08401



Photo#4:

Noxious B list weed, Scotch thistle is established on site.

November 19, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: OXY / Laramie PA Bradshaw-Dolley API#077-08401