

## Inspection Photos

Location Name: BANTA RIDGE FED 10-19-1-103

Location ID: 05-103-10411

Inspection: 679701842



**Photo 1. Location looking north.**



**Photo 2. Buried tank without labels.**

