

Inspection Photos

Location Name: BANTA RIDGE FED 16-19-1-103

Location ID: 05-103-10311

Inspection: 679701847



Photo 1. Location looking north.



Photo 2. Buried tank without labeling.

