

Inspection Photos

Location Name: BANTA RIDGE FED 15-19D-1-103

Location ID: 05-103-10263

Inspection: 679701849



Photo 1. Location looking north.



Photo 2. Tank without labeling.