

Inspection Photos

Location Name: BANTA RIDGE FED 1-18-1-103

Location ID: 05-103-10155

Inspection: 679701853



Photo 1. Location looking north.



Photo 3. Tank without labels.



Inspection Photos

Location Name: BANTA RIDGE FED 1-18-1-103

Location ID: 05-103-10155

Inspection: 679701853



Photo 3. Unmarked deadman



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources