

Inspection Photos

Location Name: BANTA RIDGE FED 8-18-1-103

Location ID: 05-103-10239

Inspection: 679701855



Photo 1. Location looking north.



Photo 2. Tank without labels.



Inspection Photos

Location Name: BANTA RIDGE FED 8-18-1-103

Location ID: 05-103-10239

Inspection: 679701855



Photo 3. Unused tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources