

Inspection Photos

Location Name: FEDERAL (TAIGA MOUNTAIN) 9-17-1S-103

Location ID: 05-103-08749

Inspection: 679701865



Photo 1. Valve not venting.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources