

Inspection Photos  
Location Name: Trindle #2  
Location ID: 307049



Colorado Oil & Gas Conservation Commission  
40.36949, -105.04233, 1489.0m, 102°  
11/26/2018 01:05:11 PM

Production facility



Colorado Oil & Gas Conservation Commission  
40.36924, -105.04238, 1493.0m, 206°  
11/26/2018 01:06:35 PM

Wellhead



**Inspection Photos**  
**Location Name: Trindle #2**  
**Location ID: 307049**



**Produced water tank placards**



**Crude oil tank placards**

**Inspection Photos**  
**Location Name: Trindle #2**  
**Location ID: 307049**



Colorado Oil & Gas Conservation Commission  
40.36957, -105.04211, 1498.0m, 241°  
11/26/2018 01:11:56 PM

**Rear of produced water tank**



Colorado Oil & Gas Conservation Commission  
40.36956, -105.04212, 1496.0m, 238°  
11/26/2018 01:12:18 PM

**Rear of produced water tank showing clean out plate and corrosion**

