

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401850919

Date Received:  
11/27/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95960

Name of Operator: WEXPRO COMPANY

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

April Stegall

307-352-7561

april.stegall@dominionenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692400200

Inspection Date: 09/26/2018

FIR Submit Date: 10/07/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: WEXPRO COMPANY

Company Number: 95960

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

LOCATION - Location ID: 313124

Location Name: CHAPMAN STATE-611N97W Number: 16SESW County: MOFFAT

Qtrqr: SESW Sec: 16 Twp: 11N Range: 97W Meridian: 6

Latitude: 40.907980 Longitude: -108.298740

FACILITY - API Number: 05-081- -00 Facility ID: 223606

Facility Name: CHAPMAN STATE Number: 2

Qtrqr: SESW Sec: 16 Twp: 11N Range: 97W Meridian: 6

Latitude: 40.907980 Longitude: -108.298740

CORRECTIVE ACTIONS:

1 CA# 119388

Corrective Action: Assess vegetation in Fall 2018; reseeding / inter-seeding/ controlling weeds /applying remedies as indicated where desirable vegetation is not Progressing.

Date: 11/30/2018

Response: CA COMPLETED

Date of Completion: 11/27/2018

Operator  
Comment:

Wexpro Company has obtained Disturbance/Reclamation Monitoring results for above listed well pad and will be using the information to determine when/if the well pad will need to be reseeded. Final reclamation dirt work and seeding of the well pad were completed in the fall of 2017, and may not have had enough time to establish. Wexpro will continue to monitor the pad yearly until Final Abandonment. The well pad is also on the yearly spray list for bareground and noxious weed treatments.



COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Wexpro Company has obtained Disturbance/Reclamation Monitoring results for above listed well pad and will be using the information to determine when/if the well pad will need to be reseeded. Final reclamation dirt work and seeding of the well pad were completed in the fall of 2017, and may not have had enough time to establish. Wexpro will continue to monitor the pad yearly until Final Abandonment. The well pad is also on the yearly spray list for bareground and noxious weed treatments.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: April Stegall

Signed: \_\_\_\_\_

Title: Reclamation Agent

Date: 11/27/2018 9:18:05 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401850941	Monitoring data
-----------	-----------------

Total Attach: 1 Files