

Inspection Photos
Operator: P O & G Operating LLC
Location Name: Hoffman #9
API: 05-017-07506



1. Lease sign

2. Oily water in unit base, south side of unit

Inspection Photos
Operator: P O & G Operating LLC
Location Name: Hoffman #9
API: 05-017-07506



3. Origin of oil, gear box cover gasket leak



4. Stained soil

Inspection Photos
Operator: P O & G Operating LLC
Location Name: Hoffman #9
API: 05-017-07506



5. North side of unit base, bull shaft gasket leak