

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2018

Submitted Date:

11/26/2018

Document Number:

693600015**FIELD INSPECTION FORM**

Loc ID 321928 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10634Name of Operator: P O & G OPERATING LLCAddress: 5847 SAN FELIPE SUITE 3200City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hudson, Glen	713-589-8186	glenn_hudson@pogresources.com	Engineer

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208568	WELL	PR	09/01/2018	OW	017-07503	HOFFMAN 8	SI

**General Comment:**

Routine inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Partially elevated gravel road through pasture.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	320 Lufkin		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Gas scrubber, cathodic generator & rectifier		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	C-66 Arrow gas engine		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		38.793660,-102.369490
Comment:	Centralized tank battery f/(Hoffman 4, 5, 7, 8, 9) 4470' East				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 208568 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** No issues observed

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**Facility ID: 208568 Type: WELL API Number: 017-07503 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well is shut in, Last production was January 2018. Centralized tank battery f/(Hoffman 4, 5, 7, 8, 9) 4470' East

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT