

Inspection # 689302443

Location Photo #1



Location Photo #2

**Inspection Photo
GGU 3-31B
API # 045-07252
Inspection # 689302443**



Location Photo #3 Battery sign has wrong information posted.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources