




00244712

## TE INSPECTION FORM



Well Name WARREN #1  
Operator ANTELOPE PROD.  
Location NW1/4-11N-66W  
Field WC

API Number 05-123-07458  
Permit # \_\_\_\_\_  
County WELD  
Inspector R. J. Smith

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) \_\_\_\_\_ Fail(N) \_\_\_\_\_ Date \_\_\_\_\_ FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_ PR \_\_\_\_\_ SI ☒

Date of Inspection Before/During Drilling \_\_\_\_\_

Surf. Csg. Size \_\_\_\_\_ Setting Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_ WOC time \_\_\_\_\_  
Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Contact \_\_\_\_\_

Date of Inspection Before/During/After Completion 6-8-90

Prod. Csg. Set? ☒ Completion Rig/Activity \_\_\_\_\_  
Drilling Pits: Closed ☒ Open \_\_\_\_\_ Wellhead Installed: ☒ Sign: Yes \_\_\_\_\_ No ☒  
Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: NONE Prod. Tanks: ( / ) 300 BBLs  
Equipment PUMP & ENGINE Meter Run: Yes \_\_\_\_\_ No ☒  
Bradenhead Press: NO ACCESS Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

## AL/PA/DA Inspection

|   |                                     |
|---|-------------------------------------|
| Date Plugged: _____                           | Date Permit Expired: _____          |
| Hole Plugged: Yes _____ No _____              | Pits Backfilled: Yes _____ No _____ |
| Material Buried: Yes _____ No _____ N/A _____ | Site Clean: Yes _____ No _____      |
| Bond Release OK: Yes _____ No _____ Fed _____ | Hole Marker: Yes _____ No _____     |

Date of Safety/Status Inspection \_\_\_\_\_

Comments: ANNULUS VALVE LEAKING NO ACTIVITY FOR SOME TIME.

Violations: Yes ☒ No \_\_\_\_\_ Notice Sent: Yes ☒ No \_\_\_\_\_ Date Sent: 6-25-90



STATE OF COLORADO  
**OIL AND GAS CONSERVATION COMMISSION**

DEPARTMENT OF NATURAL RESOURCES  
SUITE 380 LOGAN TOWER BUILDING  
1580 LOGAN STREET  
DENVER, COLORADO 80203

WILLIAM R. SMITH  
Director  
DENNIS R. BICKNELL  
Deputy Director

(303) 894-2100

ROY ROMER  
Governor

June 25, 1990

Antelope Production  
1031 Andrews Highway, Western Bldg. #101  
Midland, TX 79701

Lease: Warren #1  
County: Weld  
Location: NWNW14-11N-66W


Gentlemen:

The indicated lease(s) were inspected and the following conditions were observed to exist at the time of the inspection.

|   |  |
|---|--|
| <u>Oil accumulation in retaining pit(325)</u> | <u>Thief Hatch Open(604.a(9))</u>                              |
| <u>Skim pit needs repair(Rule 325)</u>        | <u>XX Loose Fittings(604.d)</u>                                |
| <u>Covered skim tank/pit required(325)</u>    | <u>XX Bradenhead Access(Order A-1-3)</u>                       |
| <u>Well sign required (210.a,604.c)</u>       | <u>Berms Inadequate(604.a(4))</u>                              |
| <u>Oil spilled at wellhead or battery</u>     | <u>Weeds, debris or waste material observed at site(603.g)</u> |

REMARKS: Valve on the tubing/casing annulus was leaking.

The above violation(s) should be corrected immediately and a written report submitted to this office within thirty (30) days after the work is accomplished, advising us of the date and manner of correction. Failure to comply with this request may result in penalties as provided for under statute 34-5-121 of the Oil and Gas Conservation Act.



Robert J. Van Sickle  
Field Engineer

Date of Inspection: 6-8-90  
0069v/p45