

Inspection Photos
Location Name: Latham I02 697
Facility ID #449050



Pit Facility ID #423846.

Remove liner pieces as they become exposed in landfarmed material.

Inspection Photos
Location Name: Latham I02 697
Facility ID #449050



Remove or abandon black plastic pipe.



Sandbags stored in secondary containment berm.