

Inspection Photos

Location Name: Nelson Ranches - 610N58W / 7NWNW

Location #: 317523



Photo #1

Nelson Ranches #1 (API 05-123-05787) wellsite

Stained soil

Union leak – venting

from prev. fir



Photo #2

Nelson Ranches #1 wellsite

Stained soil – Remediated

Leaking union - Removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Nelson Ranches - 610N58W / 7NWNW

Location #: 317523



Photo #3

Nelson Ranches #1 wellsite

Access sign

from prev fir



Photo #4

Nelson Ranches #1 wellsite

Access sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources