

Inspection Photos
Location Name: ALM-66N65W /11SESW
Location #: 305649



Photo #1

Alm 24-11 (API # 05-123-23304) wellsite
Shut-In



Photo #2

Alm 24-11, Alm USX E 11-13 Battery
Shut-In

