

State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

OGCC RECEPTION

Receive Date:

10/31/2018

Document Number:

401819720

## Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, or report abandonment of Off-Location Flowlines, Produced Water Transfer Systems, Domestic Taps, or Crude Oil Transfer Lines as required by the 1100 Series Rules. The Form shall also be submitted to report Grade 1 Gas Leaks from Flowlines per Rule 1104.k.

## Operator Information

OGCC Operator Number: 10633 Contact Person: Schuyler Hamilton  
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (303) 774-4017  
Address: 1801 CALIFORNIA STREET #2500 Email: schuyler.hamilton@crestonepr.com  
City: DENVER State: CO Zip: 80202  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (UNCC) that participates in Colorado's One Call notification system? Yes ☒ No ☐

## OFF LOCATION FLOWLINE

## FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 409275 Location Type: Production Facilities  
Name: MELBON RANCH-62N65W Number: 17SESW  
County: WELD  
Qtr Qtr: SESW Section: 17 Township: 2N Range: 65W Meridian: 6  
Latitude: 40.134148 Longitude: -104.693127

## FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 457807 Flowline Type: Wellhead Line Action Type: Abandonment

## OFF LOCATION FLOWLINE REGISTRATION

## Flowline End Point Riser

Latitude: 40.133985 Longitude: -104.693007 PDOP: Measurement Date: 09/02/2018  
Equipment at End Point Riser: Separator

## Flowline Start Point Location Identification

Location ID: 428103 Location Type: Well Site ☐ No Location ID  
Name: Melbon Ranch Number: 17H-M265 Pad  
County: WELD  
Qtr Qtr: SWSW Section: 17 Township: 2N Range: 65W Meridian: 6  
Latitude: 40.134742 Longitude: -104.696636

## Flowline Start Point Riser

Latitude: 40.134893 Longitude: -104.696582 PDOP: Measurement Date: 08/28/2018  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: \_\_\_\_\_ Max Outer Diameter:(Inches) 3.000  
Bedding Material: \_\_\_\_\_ Date Construction Completed: 04/17/2012  
Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: \_\_\_\_\_  
Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE ABANDONMENT**

Date: 10/17/2018

**Description of Abandonment**

Flowline was disconnected from wellhead and from separator. 135' of flowline was removed from wellhead towards separator, 925' of flowline was abandoned in place. Flowline was flushed with 25bbls fresh water prior to plugging. Flowline was verified free of hydro carbons with LEL monitor. Line was cut below ground level. Flowline was capped on both ends with 120lbs of slurry per state NTO, then backfilled on both ends.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 457806 Flowline Type: Wellhead Line Action Type: Abandonment

**OFF LOCATION FLOWLINE REGISTRATION****Flowline End Point Riser**

Latitude: 40.134028 Longitude: -104.693011 PDOP: \_\_\_\_\_ Measurement Date: 08/28/2018  
Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 428103 Location Type: \_\_\_\_\_ Well Site ☐ No Location ID  
Name: Melbon Ranch Number: 17H-M265 Pad  
County: WELD  
Qtr Qtr: SWSW Section: 17 Township: 2N Range: 65W Meridian: 6  
Latitude: 40.134742 Longitude: -104.696636

**Flowline Start Point Riser**

Latitude: 40.134966 Longitude -104.696564 PDOP: \_\_\_\_\_ Measurement Date: 08/03/2018  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: \_\_\_\_\_ Max Outer Diameter:(Inches) 3.000  
Bedding Material: \_\_\_\_\_ Date Construction Completed: 04/01/2012  
Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: \_\_\_\_\_  
Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE ABANDONMENT**

Date: 10/17/2018

**Description of Abandonment**

Flowline was disconnected from wellhead and from separator. 135' of flowline was removed from separator towards wellhead, 940' of flowline was abandoned in place. Flowline was flushed with 25bbls fresh water prior to plugging. Flowline was verified free of hydro carbons with LEL monitor. Flowline was cut below ground level. Flowline was capped on both ends with 120lbs of slurry per state NTO, then backfilled on both ends.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 10/31/2018 Email: schuyler.hamilton@crestonepr.com

Print Name: Schuyler Hamilton Title: EHS Field Technician

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  \_\_\_\_\_ Director of COGCC Date: 11/29/2018

**Attachment Check List**

| <b><u>Att Doc Num</u></b> | <b><u>Name</u></b> |
|---------------------------|--------------------|
| 401819720                 | Form44 Submitted   |

Total Attach: 1 Files