

Inspection Photos
Location Name: Borland #1
Location ID: 307150



Crude oil tank placards on 11/8/18



Crude oil tank placards on 11/29/18

Inspection Photos
Location Name: Borland #1
Location ID: 307150



Wellhead on 11/8/18



Bradenhead valve on 11/29/18

Inspection Photos
Location Name: Borland #1
Location ID: 307150



Trash on 11/8/18



Removed trash on 11//29/18