

Inspection Photos
Location Name: PLA-9 CDP
Spill/Release Point ID #459062



Location of Spill/Release Point ID #459062.




Slug catcher at Spill/Release Point ID #459062

Inspection Photos
Location Name: PLA-9 CDP
Spill/Release Point ID #459062



PBVs at pig station.



NE PBV was almost filled to capacity at the time of this inspection.

Inspection Photos
Location Name: PLA-9 CDP
Spill/Release Point ID #459062



Flow path from slug catcher through weeds.



Evidence of flow onto adjacent facility.

Inspection Photos
Location Name: PLA-9 CDP
Spill/Release Point ID #459062



Damp area extends across adjacent facility.



Flow path observed on adjacent Hilcorp facility.

Inspection Photos
Location Name: PLA-9 CDP
Spill/Release Point ID #459062



Produced water flow path extends across adjacent facility.



Apparent extent of release on adjacent Hilcorp facility.