

Inspection Photos
Location Name: I31 596 Land Application Site
Facility ID #449191



Southern portion of Facility ID #449191 land farm treatment cell.



Northern portion of land farmed material.

Inspection Photos
Location Name: I31 596 Land Application Site
Facility ID #449191



Staining on PBV.



Sandbags stored in secondary containment berm.