

Inspection Photos

Location Name: LOWER HORSE DRAW 2193

Location ID: 05-103-10005

Inspection: 679701922



Photo 1. Location looking east.



Photo 2. Deadman marker lying on ground.

