

# *Inspection Photos*

*API#077-08231*

*Operator: Koch*

*Inspection Number: 692400401*

*Inspection Date: 11/28/2018*





Photo#1:  
Overview of Location to Southeast.

November 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Koch Horseshoe Canyon PA API#077-08231



**Photo#2:**

View Southwest over what was entry & access road. It does appear sufficiently roughened to prevent unwanted vehicle access.

November 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Koch Horseshoe Canyon PA API#077-08231



Photo#3:  
Site has been seeded. Much of seed is visible on top of soil, mulch was not applied.

November 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Koch Horseshoe Canyon PA API#077-08231