

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/27/2018

Submitted Date:

11/27/2018

Document Number:

688303003

**FIELD INSPECTION FORM**

Loc ID 322183 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chesson, Bob		robert.chesson@state.co.us	
Brown, Devin		dbrown@petrosharecorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209597	WELL	SI	07/01/2017	OW	039-06502	NORDMAN TRUST 32-20	SI

**General Comment:**

Spill reported at tank battery on 11/21/2018. Form 19I, #401848504 was submitted and approved.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	lease sign at CR 21		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	update operator name on tanks, maintain contents and quantity labels that are wearing off		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Tank	>= 5 bbls	
Comment:	Outside of tank was cleaned and free oil was removed. Stained soil remains (see attached photos). Per Form 19I, "The plan is to move in a hydro-vac truck on Friday to pull up contaminated soil, load it into a truck and take it to a landfill." In addition to the Initial Report to the Director, the Operator shall make a supplemental report on Form 19 not more than 10 calendar days after the spill/release is discovered that includes an 8 1/2 x 11 inch topographic map showing the governmental section and location of the spill or an aerial photograph showing the location of the spill; all pertinent information about the spill/release known to the Operator that has not been reported previously; and information relating to the initial mitigation,		
Corrective Action:	Clean up stained soils per Rule 906 and the approved Form 19I. Notify LGD and land owner if not already done.		Date: <u>12/28/2018</u>

In Containment: Yes

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 209597 Type: WELL API Number: 039-06502 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688303023	Petroshare	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4660150">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4660150</a>