



Failed Reclamation Status

County	API	well Name	Location	Facility Status	Status Date	Mineral	Surface	Inspection Date	Inspection Status	Inspection Type	Plug	Violation	Rec Pass	Document Number	Location ID	TVD	TMD
Total Wells	0																

Interim Site Reclamation Status

County	API	well Name	Location	Facility Status	Status Date	Mineral	Surface	Inspection Date	Inspection Status	Inspection Type	Plug	Violation	Rec Pass	Document Number	Location ID	TVD	TMD
Total Wells	0																

No Reclamation Status

County	API	well Name	Location	Facility Status	Status Date	Mineral	Surface	Inspection Date	Inspection Status	Inspection Type	Plug	Violation	Rec Pass	Document Number	Location ID	TVD	TMD
BACA Wells in County: 11	009-05098	PRIDE, R H UNIT 1	NWSE 23-33S-42W	PR	03/14/2003	FEE	FEE	12/14/2017	PR	PR		N		679903569	320951		5235
	009-05148	WATKINS-FRINK-HOMSER UNIT 1	SWNE 19-32S-41W	PR	11/01/1971	FEE		07/09/2018	PR	PR		N		677900739	320958		3215
	009-05161	SCHWEITZER-NEWMAN UNIT 1	SWNE 18-32S-41W	SI	04/01/2017	FEE		01/06/2016	PR	PR		N		679900917	320960		3424
	009-06309	MCKINLEY 1-20-WD	SENE 20-33S-43W	IJ	06/15/2015	FEE	FEE	04/17/2018	AC			N		679904298	321051		3400
	009-06564	MCKINLEY 2-20	SENE 20-33S-43W	PR	12/12/1997	FEE	FEE	10/19/2017	PR	PR		N		679903265	321144	0	1746
	009-06567	COOK 2-7	SESW 7-33S-43W	PR	08/01/2012	FEE	FEE	10/30/2017	PR	PR		N		679903354	321147	0	4003
	009-06569	ALLEY 2-17	CSW 17-33S-43W	PR	06/01/2018	FEE	FEE	10/19/2017	PR	PR		N		679903264	321148	0	3407
	009-06574	GODFREY 1-19	CSW 19-33S-43W	SI	06/01/2018	FEE	FEE	10/30/2017	PR	PR		N		679903351	321151	0	1850
	009-06577	REDSTONE 2-18	CSW 18-33S-43W	PR	05/19/1998	FEE	FEE	10/30/2017	PR	PR		N		679903352	321153	0	1850
	009-06590	GAS FARM 1-17	SWNE 17-33S-43W	SI	01/01/2018	FEE	FEE	10/19/2017	PR	PR		N		679903263	321159		1850
RIO BLANCO Wells in County: 2	103-10835	HELLS HOLE 19-1	NENE 19-2S-103W	SI	08/01/2017	FEDERAL	FEE								316555	6726	6730
	103-11407	HELLS HOLE 18-9	SESE 18-2S-103W	PA	11/02/2016	FEDERAL	FEDERAL								316688	6616	6857
Total Wells	13																

Passed Reclamation Status

County	API	well Name	Location	Facility Status	Status Date	Mineral	Surface	Inspection Date	Inspection Status	Inspection Type	Plug	Violation	Rec Pass	Document Number	Location ID	TVD	TMD
Total Wells	0																
Grand Total:	13																