

Inspection Photos

Location Name: Gunderson 0993-21-05 Pad

Location ID: #452797

Inspection Date: November 19, 2018



Photo #1 – View of cuttings and earthen berm from north side.



Photo #2 – Frozen precipitation inside of cuttings berm on south side of stockpile.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources