

**Inspection Photo (s)**  
**Pitman 18-7D**  
**API # 05-045-09148**  
**Inspection # 689302487**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo (s)**  
**Pitman 18-7D**  
**API # 05-045-09148**  
**Inspection # 689302487**



**Location Photo #3, Sediment being moved off location on South side of location.**



**Location Photo #4, Sediment being moved off location on South side of location.**



**Inspection Photo (s)**  
**Pitman 18-7D**  
**API # 05-045-09148**  
**Inspection # 689302487**



**Location Photo #5, Sediment being moved off location on South side of location.**



**Location Photo #6, Sediment being moved off location on South side of location.**