

Inspection Photos

Location Name: Harrison Creek Water Treatment Facility Impoundments

Location ID: #425510 Facility ID: #441238

Inspection Date: November 19, 2018



Photo #1 – Facility sign.



Photo #2 – Operator's consultant was on location drilling monitoring wells per Remediation Project #11939 on inspection date.

Inspection Photos

Location Name: Harrison Creek Water Treatment Facility Impoundments

Location ID: #425510 Facility ID: #441238

Inspection Date: November 19, 2018



Photo #3 – View of Pond 2 from SE corner.



Photo #4 – View of Pond 3 from SE corner.



Inspection Photos

Location Name: Harrison Creek Water Treatment Facility Impoundments

Location ID: #425510 Facility ID: #441238

Inspection Date: November 19, 2018



Photo #5 – Hole in pit liner for Pond 3 located in SE corner of pit, near anchor trench. Operator was contacted on 11/21/2018 via phone to notify of hole and instructed to repair liner.



Photo #6 – Tank battery located between Pond 3 and Pond 4. Note: insulated tank lacked volume/content labels and NFPA placard on inspection date.

Inspection Photos

Location Name: Harrison Creek Water Treatment Facility Impoundments

Location ID: #425510 Facility ID: #441238

Inspection Date: November 19, 2018



Photo #7 – Unused padding and scrap metal debris stored inside of SW corner of tank battery SPCC. Operator was notified via phone on 11/21/2018 and instructed to remove debris.



Photo #8 – View of Pond 4 from SE corner.