

Inspection Photos
Location Name: Gurtler #1
Location ID: 323186



Photo 1 WH



Photo 2 TNK BTRY

Inspection Photos
Location Name: Gurtler #1
Location ID: 323186



Photo 3 Stained soil in containment next to crude oil tank



Photo 4 Weeds around ECD and sep burner