

Inspection Photos

Location Name: BAXTER PASS 43-21

Location ID: 05-103-09851

Inspection: 679701950



Photo 1. Location looking west.



Photo 2. Sign missing nearest public road of "CR 25"



Inspection Photos

Location Name: BAXTER PASS 43-21

Location ID: 05-103-09851

Inspection: 679701950



Photo 3. Location looking west.



Photo 4. Location looking southwest.



Inspection Photos

Location Name: BAXTER PASS 43-21

Location ID: 05-103-09851

Inspection: 679701950



Photo 4. Small tank next to separator without label.



Photo 6. Wellhead bull plug leaking gas along threads of small plug on top of bull plug.



Inspection Photos

Location Name: BAXTER PASS 43-21

Location ID: 05-103-09851

Inspection: 679701950



Photo 7. Container without label.



Photo 8. Barrel of fluid stored on location without label or secondary containment.

