

Inspection Photos

API#077-08110

Operator: Caerus

Inspection Number: 692400409

Inspection Date: 11/20/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from access road entry to Northwest.

November 20, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Big Creek API#077-08110



Photo#2:

View over fill slope area of Location, Reclamation appears to be In Process.

November 20, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Big Creek API#077-08110