

Inspection Photos

API#077-08504

Operator: Caerus

Inspection Number: 692400406

Inspection Date: 11/20/2018





Photo#1:
Overview of Location from access road entry to South.

November 20, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Milholland API#077-08098




Photo#2:
Site is being used for Surface Owner storage of agricultural equipment and debris.

November 20, 2018



Photo#3:
Site is being used for Surface Owner storage of agricultural equipment and debris




Photo#4:
Site is being used for Surface Owner storage of agricultural equipment and debris

November 20, 2018



Photo#5:
Site is being used for Surface Owner storage of agricultural equipment and debris

November 20, 2018



Photo#6:
Site is being used for Surface Owner storage of agricultural equipment and debris.



Photo#7:
Access road; subject of Variance Request.

November 20, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Milholland API#077-08098




Photo#8:
One unknown riser was note.

November 20, 2018



Photo#9:
Unused pipe that could be O&G related.



Photo#10:

Aerial view of Well area: subject Well circled in red; orange, circles other Wells with Variance Requests submitted; white circles Well that will most likely have variance submitted.

November 20, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Milholland API#077-08098