

# Interim Reclamation and Stormwater Inspection

November 28, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 434921

Inspection Document #: 682404236

Adams County, CO

SESE Section 12 T1S R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: AFTON /HZ PAD  
Location ID: 434921



**Photo 1.** Operator well sign.



**Photo 2.** Photo taken from the approximate wellhead, facing East. Photo illustrates that interim reclamation has not been performed. This location is not in compliance with Rule 1003 standards.



Inspection Photos  
Location Name: AFTON /HZ PAD  
Location ID: 434921



**Photo 3.** Photo taken from the approximate wellhead, facing North. See comments under Photo 2.



**Photo 4.** Photo taken from the approximate wellhead, facing West. See comments under Photo 2.

Inspection Photos  
Location Name: AFTON /HZ PAD  
Location ID: 434921



**Photo 5.** Photo taken from the northwestern location, facing West. Photo illustrates stormwater erosion discharging off location. This location is not in compliance with Rule 1002 standards. Note: Weeds (Kochia) were observed along the northern and northwestern perimeter of the location that have not been managed.



Inspection Photos  
Location Name: AFTON /HZ PAD  
Location ID: 434921



**Photo 6.** Photo taken from the northwestern location, facing Northwest. Photo illustrates unmanaged weeds.