

Interim Reclamation and Stormwater Inspection

November 28, 2018

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 439515

Inspection Document #: 682404238

Adams County, CO

SWSE Section 12 T1S R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ALICIA /PAD
Location ID: 439515



Photo 1. Operator well sign.



Photo 2. Photo taken from the southwestern cut slope, facing South. Photo illustrates an unstabilized cut slope with the evidence of rill erosion. The entire southern cut slope has not been properly stabilized. This location is not in compliance with Rule 1002 standards.

Inspection Photos
Location Name: ALICIA /PAD
Location ID: 439515



Photo 3. Photo taken from the southern perimeter of the location, facing Northwest. Photo illustrates that interim reclamation has not been performed. This location is not in compliance with Rule 1003 standards.




Photo 4. Photo taken from the southern perimeter of the location, facing North. See comments under Photo 3.

Inspection Photos
Location Name: ALICIA /PAD
Location ID: 439515



Photo 5. Photo taken from the entrance of the location, facing East. Photo illustrates stormwater erosion discharging off location. This location is not in compliance with Rule 1002 standards.

Inspection Photos
Location Name: ALICIA /PAD
Location ID: 439515



Photo 6. Photo taken from the northeastern location, facing South. Photo illustrate gully erosion off the the fill slope and is discharging off location. See comments under Photo 5.