

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2018

Submitted Date:

12/04/2018

Document Number:

692600913**FIELD INSPECTION FORM**

Loc ID 384662 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 6970 SOUTH HOLLY CIR STE 206City: CENTENNIAL State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Neher, Gray	303-771-7777	bogray@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434039	WELL	PR	07/01/2017	OW	061-06889	DONOHUE 4A-2	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers and stencils on tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by tank battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Wire panels around unit and wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Lufkin unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:	East of tank battery		
Corrective Action:		Date:	

Type: Prime Mover	# 1	
Comment:	Arrow gas engine	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		38.433460,-102.429880
Comment:	2-Production tanks south of wellhead				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	434039	Type:	WELL	API Number:	061-06889	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Tank battery is 500' S of wellhead								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT