

# Inspection Photos

12/03/2018

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 316908

Inspection Doc. Number: 682504219

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 1:** Photo from the northeast corner of the well. Photo shows anchor has not been marked in accordance with 1003.



**Photo 2:** Photos 2-6 taken from the well. Photos show equipment not needed for production remains stored on the location.



Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 3:** See comments under photo 2.



**Photo 4:** See comments under photo 2.



Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 5:** See comments under photo 2.



**Photo 6:** See comments under photo 2.



Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 7:** Photo taken from the pits, facing west. Photo shows Canada thistle plants remain evident on location. It is unclear if operator addressed corrective actions requiring weed management as no notice or FIRR was submitted, and plants may have entered winter dormancy.



**Photo 8:** See comments under photo 7.