

Inspection Photos

Operator: BP Production

API: 05-067-06991

Date: 11/9/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southern edge facing northeastward. Revegetation is progressing with grasses such as sand dropseed (*Sporobolus cryptandrus*), blue grama (*Bouteloua gracilis*), and crested wheatgrass (*Agropyron cristatum*).



Photo 3. View of the western project area from the southern edge facing northward.



Photo 4. View of musk thistle rosettes (*Carduus nutans*) within the project area. Approximately 300 individuals observed.



Photo 5. View of more musk thistles within the project area.