

Inspection Photos

Operator: BP Production

API: 05-067-08352

Date: 11/9/2018



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the southern project area from the southwestern edge facing eastward. Revegetation is progressing with grasses such as sand dropseed (*Sporobolus cryptandrus*), intermediate wheatgrass (*Thinopyron intermedium*), and crested wheatgrass (*Agropyron cristatum*).



Photo 3. View of cobble run-down in the northeastern project area that appears to be functioning.



Photo 4. View of musk thistle rosettes (*Carduus nutans*) within the project area. Approximately 100 individuals observed.