

## Inspection Photos

Location Name: COLUMBINE SPRING FEDERAL 15-9-5-103

Location ID: 05-045-06323

Inspection: 679701964



Photo 1. Location looking west.



Photo 2. Container label not readable.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: COLUMBINE SPRING FEDERAL 15-9-5-103

Location ID: 05-045-06323

Inspection: 679701964



**Photo 3. Separator stack without bird protector.**

